

Future Onsite Care Management Teams 3 bed house building in Process.



Completed Block for Care Managers home and office



Bedroom 1 View



Back kitchen entrance, 3rd Bedroom, toilet & bath



Delivered roofing sheets for House



Carpenter fixing first roof



Completed Roof : - Front, porch view



Completed roof – Back view



Completed roof - Side view



Back view ,with kitchen entrance



Internal roof



Internal roof



Front View from main road





Plastering Completed





01/01/20



01/01/20



01/01/20

Plastering Completed



Plastering Completed



Plastering Completed 4



Electrical fix & plumbing



Electrical fix & plumbing



Electrical fix & plumbing



Electrical fix & plumbing



Burglar Proof Fixing



Burglar Proof Fixing



Burglar Proof Fixing



Burglar Proof Fixing



Burglar Proof Fixing



Burglar Proof Fixing



Burglar Proof Fixing



Burglar Proof Fixing



Water Tank Stand – Container 20/10ft behind.



Water Tank stand



Fixing Windows



Windows for Toilet and bath for 2 rooms



Front length view of property



Ceiling for rooms



Side Windows for kitchen and living room



Back kitchen view



Back view – Tank, stand, Drainage systems



View from main gate



Eaves Soffit



Living room T & G ceiling



Porch T&G ceiling



Security gates for external doors



Front porch view



Side front view



Side Master bed view



Mounted water Tank and Septic Tank



Half plot view – gravel and sand



Porch T&G ceiling



Master Room view









Toilet & Shower for 2 bedrooms











Kitchen Tiles



Kitchen wall unit fitting



Light fixing – Living room and Home office Ceiling



External Light Fixing - Porch



Completed work - undercoat and first painting for whole house



Painting



Toilet for 2 bedrooms



Painting - Back of property and tanks stand



Painting – Side View

